



Home About Luxfer News Products How To Buy Support Downloads Contact

Search



## Support

Support Overview

Care & Maintenance

Frequently Asked Questions

Links To Government Resources & Other Info

Serial Numbers & Markings Explained

Technical Bulletins

Request Additional Help

Limited Warranty

# Technical Bulletins

November 12, 2003

## Dates when Luxfer changed its aluminum alloy from 6351 to 6061

Between 1987 and 1988, Luxfer Gas Cylinders discontinued use of 6351 aluminum alloy and began using a proprietary version of 6061 aluminum alloy for all its aluminum cylinder models manufactured in the United States. Listed below are the dates by model number when the transitions to the new alloy occurred. Any current Luxfer models that do not appear on this list were never made from 6351 alloy in the first place and have always been made from Luxfer's proprietary 6061 alloy.

<b>SCUBA</b>	<b>Change Date</b>	<b>CO2</b>	<b>Change Date</b>
S30, S63	5-88	C1.2, C1.5	1-89
S40	6-88	C2	11-88
S50, S92	4-88	C10	8-88
S72, S100	8-87	C5	6-88
S80	1-88	C15	11-87
S808	5-87	C20, C35	4-88
		C50	2-88
<b>SCBA</b>	<b>Change Date</b>	<b>MEDICAL</b>	<b>Change Date</b>
L7, L8, L13	9-87	M9	1-88
L13	5-88	MD15, ME24	12-87
L15	1-89		
L26	2-88		
L45	11-87	<b>INDUSTRIAL GAS</b>	<b>Change Date</b>
		N22, N150	5-88
		N33	11-88
		N60, N122	12-87
		N88	12-88

[▲ Top of Page](#)   [◀ Back to List](#)

[Home](#) | [About](#) | [News](#) | [Products](#) | [How To Buy](#) | [Support](#) | [Downloads](#) | [Contact](#)



Copyright 2002-2009 Luxfer Gas Cylinders  
A MEMBER OF THE LUXFER GROUP OF COMPANIES